

CASE STUDY

BUILDING SURVEYING – SCHEDULE OF CONDITION SURVEYS

PROJECT NAME

Flats 22, 50 Sloane Square,
London SW1X 9SN

CLIENT

Cadogan Estates Ltd.

CONSTRUCTION VALUE/CONTRACT PERIOD

n/a

CONTRACT TYPE


n/a

PROJECT DESCRIPTION

A pre-works condition survey to record the condition of adjacent flats below Flat 22 where internal refurbishment works were planned to be undertaken, as illustrated below. The adjacent flats were 12, 21, 24 and 32.

MISCELLANEOUS

To establish the current condition pre-works and then to check this survey post works to ensure there was no resultant damage. The Schedule was produced in both text and photographic formats, issued to both the owner of Flat 22 and each flat owner.



T: +44 (0)1883 740 001
M: +44 (0)7515 149 707
E: dkbrooke@brookeandassociates.co.uk
WWW.BROOKEANDASSOCIATES.CO.UK



HEAD OFFICE & POSTAL ADDRESS
The Bull Pen Castle Hill Farm House Castle Square Bletchingley Surrey RH1 4LD
LONDON OFFICE
4th Floor 169 Piccadilly London W1J 9EH

SPECIALISTS IN

Access and Oversail
Asset Management/Stock Condition Survey
Building Defect Analysis
Building Reinstatement Cost Assessments
Building Surveys
Dilapidations
Party Wall Matters
Project Management